

DAMAGE TANK REPORT

TANK NO: ICSU028666 3

LAST CARGO: FURFURAL

CLEANED DATE: March 18, 2008

SURVEY DATE: March 24, 2008

SURVEY DEPORT:*****

SURVEYOR: Robin Wang

REPORT:

1,LOCATION 1#

1) Outer state

Did not be found new

Damage evidence, The

loaction has been

repaired at unknow

place and unknow time. Much rust were found at the loaction.



2)Intior state

We are not found any damage or dent at the loacation 1#.



2, Loacation 2#

1)Outer state

We are not find new Damage evidence, The loaction has been repaired at unknow place and unknow time. Much rust were found at the loacation.



2)Interior state

We are not found any damage or dent at the loaction 2#.



3, Loaction 3#

1)Outer state


The loaction was found much rust and be repaired at unknow time and unknow place. But no found leakage evidence.





2) Interior state

Crack was found at interior of the
loactaion 3# , the crack length
about 3 cm



4, Location 4#

1) Outer state

This is leakage location.

Be repaired at unknown
place and on unknown

time. Much rust and

cargo stain were found at the location 4#. But no found any new
damage evidence.



2) Interior state

Crack, pitting and dent were found at the location 4#, The length is about 5cm, and the pitting length is about 5mm.

